

0138

Permit - Route to file
FOLDER # 2
ACT 015/032

GENWAL COAL COMPANY

RECEIVED

DEC 16 1991

DIVISION OF
OIL GAS & MINING

December 10, 1991

Mr. Daron Haddock
Division of Oil, Gas & Mining
3 Triad Center, Suite 350
355 West North Temple
Salt Lake City, UT 84180-1203

RE: Permit #ACT 015-032
Genwal Coal Company
Weekly Subsidence Inspection Report

Dear Mr. Haddock:

This letter is to inform you that Genwal Coal Company conducted a visual subsidence inspection made from the road in Crandall Canyon and Huntington Canyon on December 4, 1991. No visual subsidence was observed at this time. This visual check was made according to page 12-17 of our mining and reclamation plan. Genwal has not conducted any second mining since October 8, 1990.

Should you have any questions or need additional information, please contact me at 687-9813.

Sincerely,

GENWAL COAL COMPANY



Randal J Ralphs
Surface Foreman
Project Coordinator

tr