



Norman H. Bangertter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

April 17, 1992

Mr. Allen Childs
Genwal Coal Company, Inc.
Box 1201
Huntington, Utah 84528

Dear Mr. Childs:

Re: Division Order #92A and Proposed Mine Sequence Changes, Genwal Coal Company Inc., Crandall Canyon Mine, ACT/015/032-92C, Folder #2 and #3, Emery County, Utah

The Division has reviewed the revised information submitted on April 10, 1992 in regard to the subsidence control plan and the effects of State lease ML-21569. The Division has determined that an incidental boundary change is considered appropriate to extend the permit area along the north side of the lease.

Prior to approval of an incidental boundary change, Genwal must submit a map to the Division clearly showing the proposed permit boundary for that area, a projection of the mine workings showing specifically, which areas are to be second mined, and, the maximum extent of planned subsidence associated with the mine workings projected in State lease ML-21569.

Other deficiencies have been found in the proposal which can be conditioned on approval, or, are part of Division Order ACT/015/013 #92A. Further information regarding these deficiencies will be sent to Genwal in the near future.

Sincerely,

A handwritten signature in cursive script that reads "Daron R. Haddock".

Daron R. Haddock
Permit Supervisor

BT015032.LT2