

GENVAL COAL COMPANY

July 12, 1993

Mr. Daron Haddock
Division of Oil, Gas & Mining
3 Triad Center, Suite 350
355 West North Temple
Salt Lake City, UT 84180-1203

RECEIVED

JUL 12 1993

DIVISION OF
OIL GAS & MINING

RE: Permit #ACT 015-032
Genval Coal Company
Resubmittal, Plate 5-3, Surface Facility Map

Dear Mr. Haddock:

Please find enclosed fourteen (14) copies of the revised Plate 5-3, The Surface Facility map. Genval is resubmitting Plate 5-3 in response to a DOGM letter, dated July 7, 1993, denying approval of the construction of a new platform truck scale.


After a closer look of Plate 5-3 submitted to you, it became obvious that the size, location and alignment of the truck scale shown was in error. I inturn, went to the sight and physically surveyed the new scale location. This new submittal of Plate 5-3 reflects these conclusions. The actual location and size of the proposed platform truck scale is now shown correctly and was the only change made on this new submittal.

After talking to Mr. Walt Nowak of the Price District office of the Manti LaSal National Forest, this new submittal should satisfy his concerns in the fact that the scale will not restrict road width and will still be located within the disturbed boundaries at the Crandall Canyon Mine.

Should you have any questions or need additional information, please contact me at 687-9813.

Sincerely,


GENVAL COAL COMPANY
R. Jay Marshall
Chief Engineer


Larry W. Johnson
Engineer