



Handwritten initials/signature

NO. N 93-43-1-1

notice of violation

To the following Permittee or Operator:

Name Genwal Coal Company

Mine Crandall Canyon Mine Surface Underground Other

County Emery State Utah Telephone _____

Mailing Address P.O. Box 1281, Huntington, Utah 84528

State Permit No. ACT/015/032

Ownership Category State Federal Fee Mixed

Date of inspection 23 Sept 1993, 19 93

Time of inspection 08:30 a.m. p.m. to 12:45 a.m. p.m.

Operator Name (other than Permittee) _____

Mailing Address _____

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining is** is not expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

CERTIFIED RETURN RECEIPT

P 074 978 372

Date of service (mailing) 9/28/93

Time of service (mailing) 3:00 a.m. p.m.

Permittee/Operator representative _____

Title _____

Signature _____

James D. SMITH
Division of Oil, Gas & Mining representative

Reclamation Specialist
Title

[Signature]
Signature

#43
Identification Number

SEE REVERSE SIDE

WHITE-DOGM YELLOW-OPERATOR PINK-OSM GOLDENROD-NOV FILE



35
NOTICE OF VIOLATION NO. N 93-43-1-1

Violation No. 1 of 1

Nature of violation

A 20' by 12" culvert has been installed in diversion DD-4, but it is not shown on either Plate 3-1 (Surface Facilities) or 7-5a (Surface Runoff Control) in the current MRP. There are no design or as-built design specifications, criteria, or plans in Appendices 7-7 or 7-11 or elsewhere in the MRP

Provisions of act, regulations or permit violated

R645-301-741 Plans incorporating minimum design criteria for control of drainage

Portion of operation to which notice applies

Diversions - design criteria and plans

Remedial action required (including any interim steps)

- 1) Perform design calculations to determine if this culvert is adequately sized.
- 2) If this present culvert is adequately sized, amend the MRP to include this culvert
- 3) If this culvert is not adequate, design a properly sized culvert, amend the plan with DOG-M's approval, and replace the culvert with one of proper size.

Abatement time (including interim steps)

- 1) & 2) 30 days but no later than 5:00pm ~~October 7,~~ ^{November 4,} 1993
- 3) 60 days but no later than 5:00pm December 7, 1993