

GENWAL COAL COMPANY

July 19, 1994

Mr. Daron Haddock
 Division of Oil, Gas & Mining
 3 Triad Center, Suite 350
 355 West North Temple
 Salt Lake City, UT 84180-1203

RE: Permit #ACT 015-032
 Crandall Canyon Mine:
 USFS review of cut slope shotereting

Dear Mr. Haddock:

Please find enclosed fourteen (14) copies of a revised page 5-30A and a new page 5-30B, Figure 5-10. These changes were made to address the USFS concerns as stated in a letter from the USFS to Ms. Pamela Grubaugh-littig on June 30, 1994. Please incorporate these changes into the approved Mine and Reclamation Plan.

Should you have any questions or need additional information, please contact me at 687-9813.

Sincerely,
 GENWAL COAL COMPANY


 Larry W. Johnson

94D
 additional
 information

ACT/015/032 #2
 COPY PAM

