



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

Partial: XX Complete: Exploration
Inspection Date/Time: May 16, 1994/09:00am-01:00pm
Date of Last Inspection: April 26, 1994

Mine Name: Crandall Canyon County: Carbon Permit Number: ACT/015/032
Permittee and/or Operator's Name: Genwal Coal Company
Business Address: P.O. Box 1201, Huntington, Utah 84528
Type of Mining Activity: Underground XX Surface Prep. Plant Other
Officials(s): State: Stephen J. Demczak Company: Larry Johnson
Federal Official(s): Weather Conditions: Warm 70's
Existing Acreage: Permitted-2165.42 Disturbed-0 Regraded-0 Seeded-0 Bonded-0
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/XXXActive/ Inactive/ Temp Cessation/ Bond Forfeiture
Reclamation (Phase I/ Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

EVALUATED N/A COMMENTS NOV/ENF

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[]	[]	[]	[]
2. SIGNS AND MARKERS	[XX]	[]	[XX]	[]
3. TOPSOIL	[XX]	[]	[XX]	[]
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	[XX]	[]	[XX]	[]
b. SEDIMENT PONDS AND IMPOUNDMENTS	[XX]	[]	[]	[]
c. OTHER SEDIMENT CONTROL MEASURES	[XX]	[]	[XX]	[]
d. WATER MONITORING	[]	[]	[]	[]
e. EFFLUENT LIMITATIONS	[]	[]	[]	[]
5. EXPLOSIVES	[]	[]	[]	[]
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[]	[]	[]	[]
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[]	[]	[]	[]
8. NONCOAL WASTE	[]	[]	[]	[]
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	[]	[]	[]	[]
10. SLIDES AND OTHER DAMAGE	[]	[]	[]	[]
11. CONTEMPORANEOUS RECLAMATION	[]	[]	[]	[]
12. BACKFILLING AND GRADING	[]	[]	[]	[]
13. REVEGETATION	[]	[]	[]	[]
14. SUBSIDENCE CONTROL	[]	[]	[]	[]
15. CESSATION OF OPERATIONS	[]	[]	[]	[]
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	[]	[]	[]	[]
b. DRAINAGE CONTROLS	[]	[]	[]	[]
17. OTHER TRANSPORTATION FACILITIES	[]	[]	[]	[]
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	[]	[]	[]	[]
19. AVS CHECK (4th Quarter-April, May, June) _____ date	[]	[]	[]	[]
20. AIR QUALITY PERMIT	[]	[]	[]	[]
21. BONDING & INSURANCE	[]	[]	[]	[]

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/032

DATE OF INSPECTION: May 16, 1994

(Comments are Numbered to Correspond with Topics Listed Above)

2. Signs and Markers -

The disturbed area markers have been changed, on the ground and on maps, to reflect the correct area of disturbance in the permit area. This was noted by OSM in the last oversight inspection. The operator responded immediately to the OSM and DOGM inspectors request for the changing of the markers and map revision.

3. Topsoil -

The topsoil piles had additional straw bales installed around the perimeter. This area would appear to be a small area exemption if operator chose to demonstrate.

4a. Diversions -

The ditches were clear of sediment and were functioning as designed. There were no signs of breaching or overtopping of the ditch. Also, no eroding of the ditches was apparent.

4c. Other Sediment Control Measures -

Silt fences and straw bales were installed in ASCA areas. There were no signs of bypassing.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to: Larry Johnson (Genwal Coal Company)

Mailed to: Bernie Freeman (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: June 9, 1994

Inspector's Signature and Number: _____


Stephen J. Demczak -

#39