

GENWAL
RESOURCES, INC.

June 28, 1995

P.O. Box 1420 • 195 North 100 West • Huntington, Utah 84528
Telephone (801) 687-9813 • Fax (801) 687-9784

0048

Mr. Dave Darby
Reclamation Hydrologist
Division of Oil Gas and Mining
3 Triad Center
355 West North Temple
Salt Lake City, Utah 84180-1203

Dear Dave:

ACT 10151032 #2

As you are aware Genwal Resources, Inc. has been performing annual maintenance of our runoff diversion ditches and cleaning of the sediment pond. During the course of our work it has become apparent that both DD-5 and DD-9 (Plate 7-5A) need to be cleaned of accumulated sediment.

Therefore, it is our proposal to bring in additional rip-rap (screened 6" D-50 subangular sandstone) to maintain the integrity of our diversion and to restore the original grade. I called your office today and talked with Mr. Joe Helfrich and received verbal approval for the extended maintenance. (Appropriate care will be taken to ensure that the design capacity of the diversion is not diminished).

I would like to schedule an informal onsite visit with you during the week of July 10-14 to discuss our maintenance efforts and review any potential areas of concern. I greatly appreciate your assistance in this and other regulatory issues.

Sincerely,


Randolph B. Gainer PG
Environmental Manager

cc: Joe Helfrich