


CERTIFICATION REPORT

On JANUARY 16, 1996, an inspection of Genwal Coal Company's sedimentation pond number 1 revealed the following:

- A. The pond has been constructed and maintained in accordance with the approved plan.
- B. The pond's embankment appeared sound with no signs of instability or hazardous conditions.
- C. The water evaluation was 77.78 feet. The water depth was 7' including ice feet.
- D. The existing storage capacity is .99 acre-feet which is greater than/less than .95 acre-feet required by the Mining and Reclamation plan.
- E. The pond is inspected quarterly for signs of structural weakness or problems.

F. Comments and Remarks No signs of slippage, sluffage, erosion, piping, leakage, etc.

I have performed the above inspection on this pond to comply with R645-301-514 and do hereby certify the inspection to be a true and accurate representation of the pond at this time.



R. Jay Marshall
Signature

3/14/96
Date

Figure 5-1