

NO. N 95-47-1-1

notice of violation

To the following Permittee or Operator:
 Name Genwal Coal Company, Inc.
 Mine Crawdall Canyon Mine Surface Underground Other
 County Emery State Utah Telephone (801) 687-9813
 Mailing Address P.O. Box 1201
 State Permit No. ACT 1015/032
 Ownership Category State Federal Fee Mixed
 Date of inspection August 17, 1995, 19____
 Time of inspection 1:00 a.m. p.m. to 3:00 a.m. p.m.
 Operator Name (other than Permittee) _____
 Mailing Address P 074 976 219

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining is** **is not** expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/ mailing August 23, 1995

Time of service/ mailing 5:00 a.m. p.m.

Randolph B. Gaiser
 Permittee/Operator representative

Environmental Manager
 Title

Signature _____

DAVID DABBY
 Division of Oil, Gas & Mining representative

Reclamation Hydrologist
 Title

Daniel W. Daby
 Signature

47
 Identification Number

SEE REVERSE SIDE

WHITE-DOGM YELLOW-OPERATOR PINK-OSM GOLDENROD-NOV FILE



NOTICE OF VIOLATION NO. N 95-47-1-1

Violation No. 1 of 1

Nature of violation

Failure to conduct mining activities according to the approved plan.

Provisions of act, regulations or permit violated

R.645-300-143

Portion of operation to which notice applies

Sediment pond spillway elevation is above pond embankment elevation.

Remedial action required (including any interim steps)

Survey sedimentation pond embankment and spillway elevations. Submit survey data to DOGM and plans to level the embankment and grade spillway to conform to mine plan designs.

Abatement time (including interim steps)

Submit survey data, and plans by August 31, 1995 @ 5:00 pm. Complete reconstruction of pond embankment and spillway by September 8, 1995, as per approved plans.