



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

INSPECTION REPORT

Partial: X Complete: Exploration:
Inspection Date & Time: January 31, 1996
Date of Last Inspection: 12/14/95

Mine Name: Crandall Canyon Mine County: Carbon Permit Number: ACT/015/032
Permittee and/or Operator's Name: Genwall Resources
Business Address: P.O. Box 1210, Huntington, Utah 84501
Type of Mining Activity: Underground X Surface Prep. Plant Other
State Official(s): David W. Darby
Company Official(s): Randy Gainer
Federal Official(s): None
Existing Acreage: Permitted- 2165.42 Disturbed- 5.55 Regraded- .5 Seeded- .5 Bonded- 5.55
Increased/Decreased: Permitted- 0 Disturbed- 0 Regraded- 0 Seeded- 0 Bonded- 0
Status: Exploration/ X Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation (Phase I/Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 4 columns: EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include: PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; SIGNS AND MARKERS; TOPSOIL; HYDROLOGIC BALANCE; EXPLOSIVES; DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES; COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS; NONCOAL WASTE; PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES; SLIDES AND OTHER DAMAGE; CONTEMPORANEOUS RECLAMATION; BACKFILLING AND GRADING; REVEGETATION; SUBSIDENCE CONTROL; CESSATION OF OPERATIONS; ROADS; CONSTRUCTION/MAINTENANCE/SURFACING; DRAINAGE CONTROLS; OTHER TRANSPORTATION FACILITIES; SUPPORT FACILITIES/UTILITY INSTALLATIONS; AVS CHECK (4th Quarter-April, May, June) (date); AIR QUALITY PERMIT; BONDING & INSURANCE.



INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/032

DATE OF INSPECTION: 01/31/96

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

Randy Gainer and I toured the minesite. There was approximately 18 inches of snow in the working areas of the minesite. Snow had accumulated to even more depth in the bottom of the canyon near the stream because of drifting snow.

The DOGM is in the process of conducting a mid-term permit review. Genwal Resources also submitted an updated plan to extend the minepad south of their current minepad. The plan requires that a culvert be placed along 100 feet of the stream channel. A similar set of plans were previously submitted in October 1995. The revised plans have been distributed to other agencies for comment. While at the site, Randy stated that Genwal wants to expand in the area of the Forest Service's special use area. He proposed to keep it separate from the pad expansion, since they wanted to develop the area soon. He said he would submit a minor amendment for the development.

4. HYDROLOGIC BALANCE

a. DIVERSIONS

All disturbed and undisturbed diversions were evaluated for stability and integrity. Most of the ditches were filled with snow, but all diversions on the mine pad and access road were functioning well with no obstructions or breaches.

b. SEDIMENTATION PONDS AND IMPOUNDMENTS

The pond was partially full of water and frozen. Water is still being pumped from the pond into the mine.

Copy of this Report:

Mailed to: James Fulton (OSM, Denver), Randy Gainer (Genwal)

Given to: Joe Helfrich (DOGM)

Inspector's Signature: David W. Darby David W. Darby # 47 Date: 02/06/96