



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

Partial: XXX Complete: Exploration:
Inspection Date & Time: 10/17/96 / 7:00a.m.-11:00a.m.
Date of Last Inspection: 9/11/96

Mine Name: Crandall Canyon Mine County: Emery Permit Number: ACT/015/032
Permittee and/or Operator's Name: Genwal Resources, Inc.
Business Address: P.O. Box 1210, Huntington, Utah 84528
Type of Mining Activity: Underground XXX Surface Prep. Plant Other
Company Official(s): Gary Gray
State Officials(s): Stephen J. Demczak Federal Official(s): None
Weather Conditions: Cool, 50's
Existing Acreage: Permitted- 5036 Disturbed- 7.2 Regraded- .5 Seeded- .5 Bonded- 5.55
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ XXX Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation (Phase I/Phase II/Final Bond Release/Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include: PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; SIGNS AND MARKERS; TOPSOIL; HYDROLOGIC BALANCE; DIVERSIONS; SEDIMENT PONDS AND IMPOUNDMENTS; OTHER SEDIMENT CONTROL MEASURES; WATER MONITORING; EFFLUENT LIMITATIONS; EXPLOSIVES; DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES; COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS; NONCOAL WASTE; PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES; SLIDES AND OTHER DAMAGE; CONTEMPORANEOUS RECLAMATION; BACKFILLING AND GRADING; REVEGETATION; SUBSIDENCE CONTROL; CESSATION OF OPERATIONS; ROADS; CONSTRUCTION/MAINTENANCE/SURFACING; DRAINAGE CONTROLS; OTHER TRANSPORTATION FACILITIES; SUPPORT FACILITIES/UTILITY INSTALLATIONS; AVS CHECK (4th Quarter-April, May, June) (date); AIR QUALITY PERMIT; BONDING & INSURANCE.



INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/032

DATE OF INSPECTION: 10/17/96

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMIT -

- a) Genwal will be submitting an amendment to mining closer to the coal lease and permit boundary. The permittee will be using 1995 subsidence data to show that no subsidence will occur past the permit area.
- b) The permittee was in the process of cleaning out the sediment pond when a truck load of sediment went over the embankment off the permitted site. The permittee contacted the Division about the spill and had silt fences installed and sediment vacuumed prior to inspection. A violation was written for having a disturbance off the permit area. The violation was terminated the same day because the area was seeded, vacuumed and sediment control installed as required in the abatement.

4A. DIVERSIONS -

The diversions were spot-checked for performance standards. These ditches were clear of sediment or blockage. No violation was noticed during the inspection.

4B. SEDIMENT POND -

The permittee was in the process of cleaning out the sediment pond. The sediment is mostly coal, and therefore, will be brought back into the coal stockpile.

14. SUBSIDENCE -

The subsidence survey has started but weather conditions have hindered the completion of it.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Genwal Resources, Inc. Marcia Petta (OSM)
Given to: Joe Helfrich (DOGM) Filed to: Price Field Office
Date: October 24, 1996

Inspector's Signature: _____

Stephen J. Demezak

#39