



State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Michael O. Leavitt Governor Ted Stewart Executive Director James W. Carter Division Director

1594 West North Temple, Suite 1210 Box 145801 Salt Lake City, Utah 84114-5801 (801) 538-5340 (801) 359-3940 (Fax)

Partial: Complete: XXX Exploration: Inspection Date & Time: 2/18/98 / 8:00a.m.-12:00p.m. Date of Last Inspection: 1/23/98

Mine Name: Crandall Canyon Mine County: Emery Permit Number: ACT/015/032 Permittee and/or Operator's Name: Genwal Resources, Inc. Business Address: P.O. Box 1420, Huntington, Utah 84528 Type of Mining Activity: Underground XXX Surface Prep. Plant Other Company Official(s): Gary Gray State Officials(s): Stephen J. Demczak Federal Official(s): None Weather Conditions: Snow Cover, 24" Existing Acreage: Permitted- 5049 Disturbed- 10.20 Regraded- .5 Seeded- .5 Bonded- 10.20 Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded- Status: Exploration/ XXX Active/ Inactive/ Temporary Cessation/ Bond Forfeiture Reclamation (Phase I/Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard. a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A. b. For partial inspections check only the elements evaluated. 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below. 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below. 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: EVALUATED, N/A, COMMENTS, NOV/ENF. Rows 1-21 list various permit conditions and their status.



INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/032

DATE OF INSPECTION: 2/18/98

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMIT -

The permittee has notified the Division in writing as required in the R645 regulations to renew the Mining and Reclamation Permit.

The permittee has no minor amendment submitted for review by either the PFO or SLO.

4a. DIVERSIONS -

The diversions were spot-inspected and several diversions were covered with snow. Some of the inlets and culverts were being cleaned prior to and during the inspection.

4b. SEDIMENT POND -

The sediment pond was snow covered and contained water. This pond may discharge in the near future or possibly in the spring.

No hazardous conditions were noticed. The embankments, outlets, and inlets are covered with 24 inches of snow.

The permittee inspected the sediment pond for 4th quarter with no hazardous conditions being reported.

18. SUPPORT FACILITIES -

The new coal storage and loadout facility is complete, and the old loadout is being torn down.

21. BONDING AND INSURANCE -

The bonding agreement needs to be updated showing the current disturbed area. Forms are at the SLO.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Gary Gray (Genwal)


Henry Austin (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: February 24, 1998

Inspector's Signature: _____


Stephen J. Demczak

#39