



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

1594 West North Temple, Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801
(801) 538-5340
(801) 359-3940 (Fax)

Partial: XXX Complete: Exploration:
Inspection Date & Time: 3/9/98 / 8:00a.m.-10:00a.m.
Date of Last Inspection: 2/18/98

Mine Name: Crandall Canyon Mine County: Emery Permit Number: ACT/015/032
Permittee and/or Operator's Name: Genwal Resources, Inc.
Business Address: P.O. Box 1420, Huntington, Utah 84528
Type of Mining Activity: Underground XXX Surface Prep. Plant Other
Company Official(s): None
State Officials(s): Stephen J. Demczak Federal Official(s): Jeff Defreest, USFS
Weather Conditions: 30's, 24" Snow Cover
Existing Acreage: Permitted- 5049 Disturbed- 10.20 Regraded- .5 Seeded- .5 Bonded- 10.20
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ XXX Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation (Phase I/Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include: PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; SIGNS AND MARKERS; TOPSOIL; HYDROLOGIC BALANCE; DIVERSIONS; SEDIMENT PONDS AND IMPOUNDMENTS; OTHER SEDIMENT CONTROL MEASURES; WATER MONITORING; EFFLUENT LIMITATIONS; EXPLOSIVES; DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES; COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS; NONCOAL WASTE; PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES; SLIDES AND OTHER DAMAGE; CONTEMPORANEOUS RECLAMATION; BACKFILLING AND GRADING; REVEGETATION; SUBSIDENCE CONTROL; CESSATION OF OPERATIONS; ROADS; CONSTRUCTION/MAINTENANCE/SURFACING; DRAINAGE CONTROLS; OTHER TRANSPORTATION FACILITIES; SUPPORT FACILITIES/UTILITY INSTALLATIONS; AVS CHECK (4th Quarter-April, May, June) (date); AIR QUALITY PERMIT; BONDING & INSURANCE.



**INSPECTION REPORT**  
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/032

DATE OF INSPECTION: 3/9/98

(Comments are Numbered to Correspond with Topics Listed Above)

**1. PERMIT -**

The expansion of the coal loadout facility has been completed. The only project which is not yet completed is the addition of another lane in this area. It is to be completed in the summer when weather conditions permit.

The permittee has committed to put gravel down in this area, in the meantime, as requested by the Forest Service and DOGM. (3/10/98 phone conversation)

**4a. DIVERSIONS -**

The some of the diversions were snow covered. No water was flowing during the inspection.

**4b. SEDIMENT POND -**

The sediment pond did contain water but no discharge was noticed. The pond was snow covered and no hazardous conditions were noticed.

**16a. ROAD CONSTRUCTION -**

The USFS requested that the inspector of Genwal assist in a road inspection. The Forest Service received a complaint for the road being blocked and for a possible driving hazard at the new coal loadout facility the weekend prior to the inspection.

The site inspection was made jointly and no blockage was noticed. The area at the new facility (belt crossing the road) is a single lane. This area is scheduled to be paved and become a two lane road this summer. Since this area is congested, a request was made to gravel the area for two lane use. The permittee has committed to do this.

**Note:** This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

**Copy of this Report:**

Mailed to: Gary Gray (Genwal)

Henry Austin (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: March 10, 1998

Inspector's Signature: \_\_\_\_\_

Stephen J. Demczak  
Stephen J. Demczak

#39