



State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

gjh

Michael O. Leavitt Governor Ted Stewart Executive Director James W. Carter Division Director

1594 West North Temple, Suite 1210 Box 145801 Salt Lake City, Utah 84114-5801 (801) 538-5340 (801) 359-3940 (Fax)

Partial: XXX Complete: Exploration:

Inspection Date & Time: 4/16/98 / 10:00a.m.-1:00p.m.

Date of Last Inspection: 3/9/98

Mine Name: Crandall Canyon Mine County: Emery Permit Number: ACT/015/032 Permittee and/or Operator's Name: Genwal Resources, Inc. Business Address: P.O. Box 1420, Huntington, Utah 84528 Type of Mining Activity: Underground XXX Surface Prep. Plant Other Company Official(s): State Officials(s): Stephen J. Demczak Federal Official(s): Weather Conditions: 30's Existing Acreage: Permitted- 5049 Disturbed- 10.20 Regraded- .5 Seeded- .5 Bonded- 10.20 Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded- Status: Exploration/ XXX Active/ Inactive/ Temporary Cessation/ Bond Forfeiture Reclamation (Phase I/ Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard. a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A. b. For partial inspections check only the elements evaluated. 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below. 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below. 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: Item, EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include items like PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; SIGNS AND MARKERS; TOPSOIL; HYDROLOGIC BALANCE; DIVERSIONS; SEDIMENT PONDS AND IMPOUNDMENTS; etc.



**INSPECTION REPORT**  
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/032

DATE OF INSPECTION: 4/16/98

(Comments are Numbered to Correspond with Topics Listed Above)

**1. PERMIT -**

The permittee does not have any minor amendments submitted to the PFO.

**4a. DIVERSIONS -**

The diversions were spot-checked and maintenance will be needed on the ditch located by the oil station. Currently, there are no violation.

**4b. SEDIMENT PONDS -**

The sediment pond contained water but was not discharging during the inspection. No hazardous conditions were noticed.


**4c. OTHER SEDIMENT CONTROL MEASURES -**

The silt fences located by the topsoil storage area and turn-a-round, next to the US Forest Service Road needs to be cleaned out and re-installed. This is due to material starting to build-up from the winter runoff.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Gary Gray (Genwal) Henry Austin (OSM)  
Given to: Joe Helfrich (DOGM) Filed to: Price Field Office  
Date: April 20, 1998

Inspector's Signature:  #39  
Stephen J. Demczak