

0001



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor
Kathleen Clarke
Executive Director
Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

INSPECTION REPORT

PHL
by
JLD

Partial: XXX Complete: Exploration:
Inspection Date & Time: 01/09/2002 / 9:00 - 11:30
Date of Last Inspection: 12/12/2001

Mine Name: Crandall Canyon Mine County: Emery Permit Number: C/015/032
Permittee and/or Operator's Name: Genwal Resources, Inc.
Business Address: P.O. Box 1420, Huntington, Utah 84528
Type of Mining Activity: Underground XXX Surface Prep. Plant Other
Company Official(s): Gary Gray
State Official(s): Karl R. Houskeeper Federal Official(s): None
Weather Conditions: Overcast, Temp 10 -20°F
Existing Acreage: Permitted 5195.8 Disturbed 10.7 Regraded Seeded
Status: Active XXX

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: Item, EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include categories like PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; SIGNS AND MARKERS; TOPSOIL; HYDROLOGIC BALANCE; EXPLOSIVES; DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES; COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS; NONCOAL WASTE; PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL ISSUES; SLIDES AND OTHER DAMAGE; CONTEMPORANEOUS RECLAMATION; BACKFILLING AND GRADING; REVEGETATION; SUBSIDENCE CONTROL; CESSATION OF OPERATIONS; ROADS; OTHER TRANSPORTATION FACILITIES; SUPPORT FACILITIES/UTILITY INSTALLATIONS; AVS CHECK; AIR QUALITY PERMIT; BONDING & INSURANCE.

**INSPECTION REPORT**

(Continuation sheet)

PERMIT NUMBER: C/015/032

DATE OF INSPECTION: 01/09/2002

( COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE )

**2. SIGNS AND MARKERS**

Checked the identification sign and other markers which included the disturbed area, topsoil, and stream buffer zone. The mailing address on the ID sign has changed and the operator has plans to replace or modify the sign.

**3. TOPSOIL**

The topsoil piles were inspected. These piles are protected by berms and/or silt fences at the present time.

A study has been done by Patrick Collins to see if the topsoil piles qualify as small area exemptions. The operator has received this report and will submit the information to the Division in the near future.

**4A. HYDROLOGIC BALANCE: DIVERSIONS**

Some minor obstructions were present during the inspection in the disturbed ditch DD-5. The obstructions likely occurred during snow removal. The operator was made aware of the obstructions and they will be removed in a timely fashion.

**4D. HYDROLOGIC BALANCE: WATER MONITORING**

Third quarter 2001 water monitoring is in the EDI pipeline awaiting approval. The fourth quarter 2001 water monitoring has been completed and is in the process of being compiled prior to submission.

Inspector's Signature: \_\_\_\_\_

*Karl R. Houskeeper*  
Karl R. Houskeeper #49

Date: January 10, 2002

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining

cc: James Fulton, OSM  
Gary Gray, Genwal  
Price Field office

O:\015032.CRA\Compliance\2002\p\_0109.wpd