



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor
Kathleen Clarke
Executive Director
Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

PAL
by [signature]

INSPECTION REPORT

Partial XXX Complete \_\_\_ Exploration \_\_\_
Inspection Date: 11/13/2002 / Time: 9:00-11:30a.m
Date of Last Inspection: 10/16/2002

Mine Name: Crandall Canyon Mine County: Emery Permit Number: C/015/032
Permittee and/or Operator's Name: Genwal Resources, Inc.
Business Address: P.O. Box 1077, Price, Utah 84501
Company Official(s): Gary Gray
State Official(s): Karl R. Houskeeper Federal Official(s): None
Weather Conditions: Clear, Temp 35°F
Type of Mining Activity: Underground XXX Surface \_\_\_ Prep Plant \_\_\_ Other \_\_\_
Existing Acreage: Permitted 5195.8 Disturbed 10.7 Regraded \_\_\_ Seeded \_\_\_
Status: Active

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include categories like PERMITS, SIGNS AND MARKERS, TOPSOIL, HYDROLOGIC BALANCE, etc.

INSPECTION REPORT  
(Continuation Sheet)

PERMIT NUMBER: C/015/032

DATE OF INSPECTION: 11/13/2002

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

**GENERAL COMMENTS**

Blasting notification was discussed with the operator during the inspection. The operator was instructed that a record of blasting, including notifications to all interested parties needs to be retained by the operator. This information should be available for inspection by the Division.

**2. SIGNS AND MARKERS**

The Mine ID sign is located at the interface of the permit boundary and the access road. The sign has been updated with a new address; however, the updated information has faded and is no longer detectable. The old address remains on the sign. The operator was instructed to upgrade the sign in a manner that gives the proper address, i.e. removing the old address and displaying the new address with a material that resists fading.


**4A. HYDROLOGIC BALANCE: DIVERSIONS**

Small amounts of snow were present throughout the mine site from recent storm events. Minimal amounts of snow have entered various diversions as part of the snow removal process. The amount of snow present in the diversions during the inspection did not impede the function of the diversions. The operator was cautioned that if the diversions do not function as designed because of the placement of snow in them that enforcement action would be taken. Care should be taken during the removal of snow to assure that the diversions continue to function as designed.

**4D. HYDROLOGIC BALANCE: WATER MONITORING**

Third quarter 2002 water monitoring has been collected. The third quarter 2002 information has not been submitted into the EDI website. Water monitoring for the fourth quarter 2002 is in process.

Inspector's Signature: \_\_\_\_\_

  
Karl R. Houskeeper #49

Date: November 13, 2002

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM  
Gary Gray, Genwal  
Price Field office

O:\015032.CRA\Compliance\2002\p\_1113.doc