

Outgoing  
C0150032  
#3614  
R



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

**State of Utah**  
**DEPARTMENT OF NATURAL RESOURCES**  
**Division of Oil, Gas & Mining**

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

November 18, 2010

Dave Shaver, Resident Agent  
Genwal Resources, Inc.  
P.O. Box 910  
East Carbon, Utah 84520-0910

Subject: Midterm Permit Review, Genwal Resources, Inc., Crandall Canyon Mine, Permit # C/015/0032 and Project # 3614

Dear Mr. Shaver:

The Division of Oil, Gas and Mining has (the Division) completed its midterm review of the Crandall Canyon Mining and Reclamation Plan (MRP).

The Division has determined that there are deficiencies to be addressed. The deficiencies are listed as an attachment to this letter. The initials of each deficiencies author are provided so that your staff can communicate directly with that individual should questions arise.

This concludes the Division's midterm review of the Crandall Canyon MRP. Please respond to the deficiencies by December 18, 2010. If you have any questions please call me at (801) 538-5325 or Steve Christensen at (801) 538-5350.

Sincerely,

A handwritten signature in cursive script that reads "Daron R. Haddock".

Daron R. Haddock  
Permit Supervisor

DRH/SKC/sqs  
cc: Price Field Office  
O:\015032.CRA\WG3614\WG3614MdTrm\_DefLtr.doc

**Deficiency List**  
**Task No. 3614**  
**Midterm Review**

Priscilla Burton (PB)  
James Owen (JO)

**R645-301-121.100-** Section 2.31.4 of the MRP refers to Appendix 2-4 for the justification and rationale for a 6 inch topsoil redistribution depth. This reference and discussion appears inconsistent with the redistribution volumes reported in Section 2.42, page 2-10 and the total stored topsoil volumes reported in on page 2-11. Please bring Section 2.31.4 of the MRP up to date and remove the Appendix 2-4 justification. (PB)

**R645-301-800-** The Permittee must provide updated direct cost estimates for the demolition, backfilling and grading, and revegetation work associated with the disturbed areas located within the permit boundary. (JO)