

**UtahAmerican Energy, Inc.**



C/015/032 Incoming

**Genwal Resources, Inc.**  
P. O. Box 910  
East Carbon, Utah 84520  
Phone: (435) 888-4000  
(435) 650-3157  
Fax: (435) 888-4002

R  
#4295

May 6, 2013

Mr. Daron Haddock,  
Permit Manager  
1594 West North Temple,  
Suite 1210,  
P.O. Box 145801,  
Salt Lake City, Utah 84114-5801.

RECEIVED  
MAY 09 2013  
DIV. OF OIL, GAS & MINING

**Re: Request Extension to Actions Required, Citation #10105, Crandall Canyon Mine, DOGM Permit C\015\032**

Dear Mr. Haddock,

On March 18, 2013 UEI received violation #10105 at the Crandall Canyon Mine. On April 5, 2013 the violation was modified. On April 10, 2013 UEI conferenced both the fact of the violation and the proposed assessment. UEI has not yet been notified of the results of the conference.

During the conference on April 10, 2013 UEI agreed to clean out the sediment pond. The preferred plan for pond cleaning was to pump the sludge into trucks and haul to Burma, this was attempted but was not successful.

As a secondary plan UEI planned to de-water the sediment pond, allow the sediment to dry and then remove the material at a location where the previous pond cleaning sediment is currently being stored.

With the spring thaw and various moisture events the de-watering was slower than anticipated. However, the pond has now been de-watered and is drying. On May 07 the pond will be surveyed to determine the amount of sediment. Around May 9<sup>th</sup> UEI will begin removing the dried sediment.

Once the sediment has been removed the pond will be re-surveyed and certified to determine the amount of the material removed and cleanout elevations.

Should you have any questions please call.

Sincerely,

R. Jay Marshall P.E.  
Project Manager