



Suzanne Steab <suzannesteab@utah.gov>

Re: Excess Spoil and behind pond 4

Priscilla Burton <priscillaburton@utah.gov>

Wed, Jun 3, 2015 at 4:32 PM

To: Keenan Storrar <kstorrar@utah.gov>, Daron Haddock <daronhaddock@utah.gov>, Suzanne Steab <suzannesteab@utah.gov>

Cc: Cheryl Parker <cherylparker@utah.gov>, Steve Christensen <stevechristensen@utah.gov>

Keenan's pictures show that they are still working on the area that they have requested bond release! The excess spoil pile photo shows them working in the area of Pit 1A to Pit 8 or BRP1-5. The bond release application PUBLIC NOTICE says this area has achieved final grade, subsoil placement and shaping for drainage control and that the work was completed in 2013 and 2014. THEREFORE the public notice is NOT ACCURATE. They must state the correct date for completion of this area.

Priscilla Burton, MS, CPSSc
Environmental Scientist III
Utah Division of Oil, Gas & Mining
Price Field Office
phone: [435-613-3733](tel:435-613-3733)

On Wed, Jun 3, 2015 at 3:06 PM, Keenan Storrar <kstorrar@utah.gov> wrote:

Here's a couple photos from yesterday.

1. The Excess spoil pile is almost gone and they had the excavator working on it. To the upper right of the trucks they have begun spreading subsoil.
2. They lifted the area behind Pond 4. Joe the surveyor was out there making sure it was lifted to the correct height. Hopefully, it will work out. The inlet is not as smooth as I'd like to see it, but I think it'll be fine in the long run because it will be re-graded when they remove the pond.

Keenan Storrar
Utah Division of Oil, Gas and Mining
[801-538-5345](tel:801-538-5345)
kstorrar@utah.gov



