



State of Utah
 DEPARTMENT OF NATURAL RESOURCES
 MICHAEL R. STYLER
Executive Director
 Division of Oil, Gas and Mining
 JOHN R. BAZA
Division Director

Technical Analysis and Findings

Utah Coal Regulatory Program

April 8, 2016

PID: C0250005
TaskID: 5153
Mine Name: COAL HOLLOW
Title: 2015 ANNUAL REPORT AMENDMENT

Operation Plan

Topsoil and Subsoil

Analysis:

The information provided does not meet the requirements of R645-301-241, because the lab analysis for samples taken during November 2015 are missing.

Deficiencies Details:

The information provided does not meet the requirements of R645-301-241, because the lab analysis for samples taken during November 2015 are missing.

pburton

Reclamation Plan

Maps Reclamation BackFilling and Grading

Analysis:

Dwg 5-38 does not meet the requirements of R645-301-121.200, because it is not clear how many acres remain to be reclaimed due to the re-use of the reclaimed excess spoil pile. It is recommended that those areas called out by color for 2012, 2013, and 2014 only reflect the area that is still reclaimed. The area identified by a hatch mark and identified in the legend as 2016 = 16 acres reclaimed after removal of Excess Spoils should not have a color associated with those previous years.

Deficiencies Details:

Dwg 5-38 does not meet the requirements of R645-301-121.200, because it is not clear how many acres remain to be reclaimed due to the re-use of the reclaimed excess spoil pile. It is recommended that those areas called out by color for 2012, 2013, and 2014 only reflect the area that is still reclaimed. The area identified by a hatch mark and identified in the legend as 2016 = 16 acres reclaimed after removal of Excess Spoils should not have a color associated with those previous years.

pburton