



GARY R. HERBERT  
Governor

SPENCER J. COX  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

### Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

April 8, 2016

Kirk Nicholes, Resident Agent  
Alton Coal Development, LLC  
463 North 100 West, Suite 1  
Cedar City, Utah 84720

Subject: Revised Drawing 5-3B, Alton Coal Development, LLC, Coal Hollow Mine, C/025/0005, Task ID #5152

Dear Mr. Nicholes:

The Division has reviewed your application. The Division has identified deficiencies that must be addressed before final approval can be granted. The deficiencies are listed as an attachment to this letter.

The deficiencies authors are identified so that your staff can communicate directly with that individual should questions arise. The plans as submitted are denied. Please resubmit the entire application by no later than April 22, 2016.

If you have any questions, please call me at (801) 538-5325.

Sincerely,

Daron R. Haddock  
Coal Program Manager

DRH/sqs

O:\025005.COL\WG5152 REVISED DRAWING 5-3B\Deficiencies.doc



**GARY R. HERBERT**  
Governor  
**GREG BELL**  
Lieutenant Governor

**State of Utah**  
**DEPARTMENT OF NATURAL RESOURCES**  
MICHAEL R. STYLER  
*Executive Director*  
**Division of Oil, Gas and Mining**  
JOHN R. BAZA  
*Division Director*

## **Technical Analysis and Findings**

### **Utah Coal Regulatory Program**

April 8, 2016

**PID:** C0250005  
**TaskID:** 5152  
**Mine Name:** COAL HOLLOW  
**Title:** REVISED DRAWING 5-3B

#### **Operation Plan**

#### **Maps Facilities**

##### *Analysis:*

###### **Analysis:**

Drawing 5-3B does not meet the requirements of R645-301-512.120 or R645-301-521.100, because the map was field checked on 4/6/2016 and found to be inaccurate. The map was marked with corrections and they were discussed with ACD's engineer, Drew Christensen.

##### *Deficiencies Details:*

###### **Findings:**

Drawing 5-3B does not meet the requirements of R645-301-512.120 or R645-301-521.100, because the map was field checked on 4/6/2016 and found to be inaccurate. The map was marked with corrections and they were discussed with ACD's engineer, Drew Christensen.

pburton