



**Action Taken on Existing Citation
Utah Coal Regulatory Program**

1594 West North Temple, Salt Lake City, UT 84114
Phone: (801) 538 - 5285 Fax: (801) 359-3940

Action on Citation#: **21166**

Permit Number: **C0250005**

Date Cit. Issued: **03/09/2016**

<input type="checkbox"/> MODIFICATION of	<input checked="" type="checkbox"/> TERMINATION of	<input type="checkbox"/> VACATION of
<input checked="" type="checkbox"/> NOTICE OF VIOLATION	<input type="checkbox"/> CESSATION ORDER (CO)	<input type="checkbox"/> FAILURE TO ABATE CO

Permittee Name: ALTON COAL DEVELOPMENT LLC	Inspector Number and ID: 37 PBURTON
Mine Name: COAL HOLLOW	Date and Time of Action: 04/12/2016 3:00 pm
Certified Return Receipt Number: <i>emailed</i>	Date and Time of Service: 04/12/2016 3:30 pm

In accordance with the provisions of the Utah Coal Mining and Reclamation Act, Utah Code Ann. § 40-10-1 et. seq. (Act), the above referenced Citation is:

Modified as follows:

Reason for modification:

Terminated because:
At ponds 1 and 2, gaskets were installed at the connection of the oil skimmer and the discharge pipe. The water level in both ponds was observed on 4/6/2016 to be well below the level of the discharge pipe, so the success of the gasket fix cannot be ascertained until the water level is at or above the discharge pipe. However, the Permittee is confident that the gasket was the problem, as the manufacturer recommended installation of the gasket, but this installation had been overlooked by the contractor during the initial construction of the ponds.

Vacated because:

KIRK NICHOLS

(Print) Permittee Representative

PRISCILLA BURTON

(Print) DOGM Representative

Permittee Representative's Signature - Date

DOGM Representative's Signature - Date

Refer to the "Citation For Non-Compliance" for additional information