

0002



SCOTT M. MATHESON
Governor

OIL, GAS, AND MINING BOARD

GORDON E. HARMSTON
Executive Director,
NATURAL RESOURCES

STATE OF UTAH

DEPARTMENT OF NATURAL RESOURCES

CHARLES R. HENDERSON
Chairman

CLEON B. FEIGHT
Director

DIVISION OF OIL, GAS, AND MINING

1588 West North Temple
Salt Lake City, Utah 84116
(801) 533-5771

JOHN L. BELL
C. RAY JUVELIN
THADIS W. BOX
CONSTANCE K. LUNDBERG
EDWARD T. BECK
E. STEELE McINTYRE

February 25, 1980

Mr. Kerry Frame
Mine Engineer
Southern Utah Fuel Co.
Salina, Utah 84654

#7

RE: SUFCO
Convulsion Canyon Mine
ACT/041/002

Dear Mr. Frame:

As you will recall, Mr. Thomas Suchoski of the Division's staff visited SUFCO's Convulsion Canyon Mine on the 20th of February, 1980 for the purpose of inspecting the mine facilities as to compliance with the interim program regulations.

No violations were issued from this inspection, though several areas of concern were noted (from the inspection and from the enclosed inspection report).


1. The pad area near the exhaust fan above the shop facilities needs to be upgraded to prevent ponding of runoff waters.
2. The mine water discharge facilities need to be upgraded to control oil and grease discharge.

It is hoped that Southern Utah Fuel Company will work on these areas of concern. The Division greatly appreciates SUFCO's help on past concern areas.

Sincerely,

DENISE A. DRAGOO
SPECIAL ASSISTANT ATTORNEY GENERAL

AND


THOMAS J. SUCHOSKI
RECLAMATION HYDROLOGIST

DAD/TJS:te
Enclosure: Inspection Report
cc: Don Crane, O.S.M.