

0053



**Southern Utah
Fuel Company**

P.O. Box P
Salina, Utah 84654
(801) 529-7428
(801) 637-4880 (Mine)

File ACT/041/002 #2 #3

Subsidiary of
Coastal States
Energy Company

copy to Sue, Rick

Susan C. Linner
Department of Oil, Gas, and Mining
4241 State Office Building
Salt Lake City, Utah 84114

Dear Ms. Linner:

The areas of concern pointed out in your October 31, 1983 letter are addressed below:

1. Reference Area. The corners of the reference area have been marked with metal fence posts. The road is not included in the reference area. Coordinates of the corners will be established by the SUFCo surveyors in the coming year for future reference.
2. Reclamation of Leach Field. The disturbed areas associated with the old and new Leach fields have been regraded and seeded. Vegetation is beginning to establish itself.
3. The Mud Spring Hollow Culvert. The Mud Spring Hollow Culvert will be paved as stated in the MRP at the beginning of the 1984 construction season, after the spring snow melt.
4. Headwall for East Spring Canyon. The headwall required for ESC culvert is 7.1 feet high, 7.1 feet is available.

Yours very truly,
SOUTHERN UTAH FUEL COMPANY

Kerry A. Frame
Chief Engineer

WKS:cfc

RECEIVED

NOV 23 1983

**DIVISION OF
OIL, GAS & MINING**