



NO. N 86-9-7-1

To the following Permittee or Operator:

Name Southern Utah Fuel Company

Mine Convulsion Canyon  Surface  Underground  Other

County Sevier State Utah Telephone 801/637-4880

Mailing Address P.O. Box P

State Permit No. ACT/041/002

Ownership Category  State  Federal  Fee  Mixed

Date of inspection 5-21-86, 19 86

Time of inspection 1:30  a.m.  p.m. to 4:00  a.m.  p.m.

Operator Name (other than Permittee) as above

Mailing Address as above

notice of violation

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining is**  **is not**  expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/mailling 6-17-86 Time of service/mailling 4:30  a.m.  p.m.

Mike Davis  
Permittee/Operator representative

Mine Engineer  
Title

Mike Davis  
Signature

Holland Shephard  
Division of Oil, Gas & Mining representative

Mining Field Specialist  
Title

Holland Shephard  
Signature

#9  
Identification Number

SEE REVERSE SIDE

WHITE-DOGDM YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE



NOTICE OF VIOLATION NO. N 86-9-7-1

Violation No. 1 of 1

Nature of violation

Failure to meet federal effluent limitations for an NPDES permitted discharge point.

Provisions of act, regulations or permit violated

U MC 817.42 (b)  
UCA 40-10-18 (i)(B)

Portion of operation to which notice applies

The parameter, TDS, was determined to be out of compliance with the operator's NPDES discharge permit. The discharge point sampled is located at the mine sediment pond.

Remedial action required (including any interim steps)

Submit in writing, to the Division, an explanation as to what may have caused the high TDS levels; and what steps the operator intends to take to prevent a future reoccurrence of the situation.

Abatement time (including interim steps)

July 7, 1986