

0004



**Southern Utah
Fuel Company**

P.O. Box P
Salina, Utah 84654
(801) 529-7428
(801) 637-4880 (Mine)

*41
HOT/1/002*

*orig min file
a L. Paragon*

Subsidiary of
Coastal States
Energy Company

RECEIVED
FEB 17 1987

**DIVISION OF
OIL, GAS & MINING**

February 12, 1987

Dr. Dianne R. Nielson
Division of Oil, Gas & Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, UT 84180-1203

Dear Dr. Nielson:

For your information, please find enclosed a copy of Southern Utah Fuel Company's quarterly sediment pond inspection report conducted February 10, 1987.

Sincerely,
SOUTHERN UTAH FUEL COMPANY

Mike Davis

Mike Davis
Construction Engineer

MD:cfc

Enclosure

MD 2/8/84
RECEIVED
FEB 17 1987

SOUTHERN UTAH FUEL COMPANY

Sediment Pond Quarterly Inspection Report

DIVISION OF
OIL, GAS & MINING

Inspector Mike Davis Date 2-10-87

1. Dam Structural Weakness

A. Cracks or scarps on crest None Observed

B. Cracks or scarps on slope None Observed

C. Sloughing or bulging on slope None Observed

2. Major Erosion Problems None Observed

3. Surface Movements of Surrounding Slopes None Observed

4. Visible Sumps or Sinkholes in Slurry Surface None Observed

5. Clogging

A. Spillway channels and pipes None Observed

B. Decant system None Observed

C. Diversion ditches None Observed

6. Seepage (Specify Location, Color and Approximate Volume) _____
None Observed

7. Other Comments Pond is frozen over

