

0048



Southern Utah Fuel Company

a subsidiary of The Coastal Corporation

P.O. Box P • Salina, Utah 84654 • (801) 529-7428
Mine: (801) 637-4880

*Big mine file
route to L Braxton #2
File A/C 10/1/82*

RECEIVED
AUG 25 1988

DIVISION OF
OIL, GAS & MINING

August 22, 1988

Dr. Dianne R. Nielson
Division of Oil, Gas & Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, UT 84180-1203

Dear Dr. Nielson:

For your information, please find enclosed a copy of Southern Utah Fuel Company's quarterly sediment pond inspection report conducted August 15, 1988.

Sincerely,
SOUTHERN UTAH FUEL COMPANY

Mike Davis

Mike Davis
Construction Engineer

MD:cfc

Enclosure

SOUTHERN UTAH FUEL COMPANY

Sediment Pond Quarterly Inspection Report

Inspector Mike Davis Date Aug 15-1988

1. Dam Structural Weakness

A. Cracks or scarps on crest None observed

B. Cracks or scarps on slope None observed

C. Sloughing or bulging on slope None observed

2. Major Erosion Problems None observed

3. Surface Movements of Surrounding Slopes No surface movement observed -

4. Visible Sumps or Sinkholes in Slurry Surface None observed

5. Clogging

A. Spillway channels and pipes None observed

B. Decant system None observed - system closed

C. Diversion ditches None Observed

6. Seepage (Specify Location, Color and Approximate Volume) _____
None observed

7. Other Comments _____

