

0009



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

DRH
JCH

Norman H. Bangertter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: May 30, 1990
7:00 am to 12:30 pm

Permittee and/or Operators Name: Southern Utah Fuel Company
Business Address: 397 South 800 West Salina, Utah 84654
Mine Name: Convulsion Canyon Permit Number: ACT/041/002
Type of Mining Activity: Underground XXX Surface Other _____
County: Sevier
Company Official (s): Mike Davis
State Official(s): Harold G. Sandbeck
Partial: _____ Complete: XXX Date of Last Inspection: March 19, 1990
Weather Conditions: Cloudy, cool with rain
Acreage: Permitted 17301 Disturbed 24.3 Regraded _____ Seeded _____ Bonded 67.8
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(XX)	()	()	()
2. SIGNS AND MARKERS	(XX)	()	()	(XX)
3. TOPSOIL	(XX)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(XX)	()	()	()
b. DIVERSIONS	(XX)	()	()	(XX)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(XX)	()	()	(XX)
d. OTHER SEDIMENT CONTROL MEASURES	(XX)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	(XX)	()	()	(XX)
f. EFFLUENT LIMITATIONS	(XX)	()	()	()
5. EXPLOSIVES	(XX)	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	(XX)	()	()	()
7. COAL PROCESSING WASTE	(XX)	()	()	()
8. NONCOAL WASTE	(XX)	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(XX)	()	()	()
10. SLIDES AND OTHER DAMAGE	(XX)	()	()	()
11. CONTEMPORANEOUS RECLAMATION	(XX)	()	()	()
12. BACKFILLING AND GRADING	(XX)	()	()	()
13. REVEGETATION	(XX)	()	()	()
14. SUBSIDENCE CONTROL	(XX)	()	()	()
15. CESSATION OF OPERATIONS	()	()	(XX)	()
16. ROADS				
a. CONSTRUCTION	(XX)	()	()	()
b. DRAINAGE CONTROLS	(XX)	()	()	()
c. SURFACING	(XX)	()	()	()
d. MAINTENANCE	(XX)	()	()	()
17. OTHER TRANSPORTATION FACILITIES	(XX)	()	()	()
18. SUPPORT FACILITIES UTILITY INSTALLATIONS	(XX)	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/041/002

DATE OF INSPECTION May 30, 1990

(Comments are Numbered to Correspond with Topics Listed Above)

2. Signs and Markers.

Signs and markers were inspected throughout the mine site. No problems were noted.

4. Hydrologic Balance.

b. Diversions.

The diversions were inspected and appear to be functioning as designed.

c. Sediment Ponds and Impoundments.

The 1st quarter 1990 pond inspection report was inspected and appears to be in order. No other problems were noted.

e. Surface and Groundwater Monitoring.

The water monitoring data was reviewed. No problems were noted.

Copy of this Report:

Mailed to: Mike Davis (Southern Utah Fuel Co) & Brian Smith (OSM)

Given to: Daron Haddock and Joe Helfrich - DOGM

Inspectors Signature and Number: *David R. Jones* #27 Date: 6/11/90