



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangarter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: October 16, 1990
8:30 a.m. - 11:30 a.m.

Permittee and/or Operators Name: Southern Utah Fuel Company
Business Address: P. O. Box P, Salina, Utah 84654
Mine Name: Convulsion Canyon Number: ACT/041/002
Type of Mining Activity: Underground Surface Other
County: Sevier
Company Official(s): Mike Davis
State Official(s): Lynn Kunzler and Steve Demszak
Partial: Complete: Date of Last Inspection Sept 26, 1990
Weather Conditions: Clear
Acreage: Permitted 7395 Disturbed 24.3 Regraded .5 Seeded .5 Bonded 67.8
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	(X)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	(X)	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS:				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/041/002

DATE OF INSPECTION: Oct. 16, 1990

(Comments are Numbered to Correspond with Topics Listed Above)

4c. Sediment Ponds and Impoundments. SUFCo was in the process of decanting the sediment pond below the mine facilities (002). Discharge was at 9 GPM and a split water sample was taken of the discharge, with SUFCo and the Division each retaining one of the splits.

16b. Roads - Drainage Control. The culvert that conveys road drainage around the substation area has been maintained as requested during the last inspection.

Copy of this Report:

Mailed to: Brian Smith - OSMRE, Mike Davis SUFCo, PFO

Given to: Joe Helfrich & Daron Haddock - DOGM

Inspectors Signature and Number: _____



#17 Date: 10/22/90