



NO. N 90-39-1-1

To the following Permittee or Operator:

Name Southern Utah FUEL Company

Mine CONVULSION CANYON MINE  Surface  Underground  Other

County Sevier State Utah Telephone 529-7428

Mailing Address P.O. BOX P SALINA UTAH 84654

State Permit No. ACT/041/002

Ownership Category  State  Federal  Fee  Mixed

Date of inspection NA, 19\_\_\_\_

Time of inspection NA  a.m.  p.m. to  a.m.  p.m.

Operator Name (other than Permittee) NA

Mailing Address \_\_\_\_\_

notice of violation

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining is**  **is not**  expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/ mailing 11-26-90 Time of service/ mailing 3:00  a.m.  p.m.

Permittee/Operator representative \_\_\_\_\_ Title \_\_\_\_\_

Signature STEPHEN J DEMCZAK  
 Division of Oil, Gas & Mining representative

Signature Stephen J Demczak

Title Reclamation Specialist

Identification Number # 39

SEE REVERSE SIDE

WHITE-DOGM YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE



NOTICE OF VIOLATION NO. N 90-39-1-1

Violation No. 1 of 1

Nature of violation

*Failure to conduct mining activities in accordance with the terms and conditions of the permit. Specifically UPDS permit No. UT0022918 (See attach letter)*

Provisions of act, regulations or permit violated

*R 614-300-142 & R 614-300-143  
UCA 40-10-17*

Portion of operation to which notice applies

*UPDES Permit*

Remedial action required (including any interim steps)

*Supply the following: a) A description of the potential causes for the high TDS concentrations being discharged b) A description of any changes in dust control procedures c) A summary of any steps being taken by SUFCO to reduce the TDS concentration in the effluent.*

Abatement time (including interim steps)

*12-26-90*