

0002



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

RECEIVED
JAN 22 1991

DEPT. OF
OIL, GAS & MINING

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

PERMIT NO.: ACT/041/002
Inspection Date: January 10, 1991

Permittee and/or Operators Name: Southern Utah Fuel Company
Business Address: P.O. Box P
City: Salina State: Utah Zip: 84654
Mine Name: Convulsion Canyon
County: Sevier County State: Utah
Type of Mining Activity: Underground Surface Other
Company Official (s): _____
State Officials (s): Stephen J. Demczak
Time of Inspection: 9:00 (X) a.m. () p.m. to 10:25 (X) a.m. () p.m.
Partial Complete: _____ Date of Last Inspection: 12/12/90
Weather Conditions: Cold/1" - 5" Snow
Acreage: Permitted 17,301 Disturbed 26.2 Regraded .5 Seeded .5
Bonded 67.8 Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	(X)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(X)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	(X)	()	()	()
8. NONCOAL WASTE	(X)	()	()	(X)
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT COMMENTS
(continuation sheet)

Page 2 of 2

PERMIT NO. ACT/041/002 INSPECTION DATE January 10, 1991

(Comments are Numbered to Correspond with Topics Listed Above)

4. HYDROLOGIC BALANCE:

d. Other Sediment Control Measures:

Sediment control measures such as silt fences were intact and operating properly. There was no water flow on the property due to cool weather. The culverts by the sub-station were clear and functional.

8. NONCOAL WASTE:

There were several pop and food containers laying in the parking lot. I advised the operator to clean up the area. The operator conceded there was a problem and said he would advise employees during Annual Retraining classes in February. The operator will clean the litter as soon as possible.

Copy of report:

Mailed to: Southern Utah Fuel Company
Mailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)
Filed to: PFO

Inspectors Signature and Number: Stephen J. Demczak #39
Date: 1/16/91 *Stephen J. Demczak*