

0003



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

DR 74
goh

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: 2/20/92
11:30 am - 1:30 pm

Permittee and/or Operator's Name: BHP Petroleum UT International
Business Address: 550 California Street, San Francisco, CA 94104
Mine Name: Knight Mine Permit Number: ACT/041/005
Type of Mining Activity: Underground Surface Other
County: Sevier Company Official(s): None
State Officials(s): Sharon Falvey,
Federal Official(s): None
Partial: Complete Date of last Inspection: 12/10/92
Weather Conditions: Partly Cloudy
Acreage: Permitted 1988 Disturbed 40 Regraded 40 Seeded 40
Bonded 40 Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(x)	()	()	(x)
2. SIGNS AND MARKERS	(x)	()	()	(x)
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(x)	()	()	(x)
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	(x)	()	()
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	(x)	()	()	(x)
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/041/005

DATE OF INSPECTION: 2/20/92

(Comments are Numbered to Correspond with Topics Listed Above)

The site was snow covered with approximately 4" of snow in shallow areas to drifts greater than 1'. Numerous animal tracks were visible.

1. PERMITS

The operator met with Division personal on February 5, 1992 to discuss bond release processes. The operator expects to apply for Phase I Bond release in early April. The operator also indicated they felt they met the requirements of the stipulations outlined as outstanding in the January 10, 1992 letter from Associate Director Lowell Braxton. In the meeting the Division indicated it would inform the applicant which stipulations are complied with in a forthcoming letter.

Revisions and as-builts of Stage II reclamation were submitted to the Division on December 31, 1991.

2. SIGNS AND MARKERS

The sign showing current operator status is present at the entrance to the minesite.

4. Hydrologic Balance:

b. Stream Channel Diversions

Stream channel diversions and culverts contained snow. No recent flow through the structures was evident.

10. SLIDES AND OTHER DAMAGE

No evidence of slope or drainage structure de-stabilization was apparent.

Copy of this Report:

Mailed to: BHP Petroleum-Knight Mine, Bernie Freeman OSM,

Given to: Daron Haddock, Joe Helfrich, DOGM

Inspector's Signature & Number: Sharon Falvey #38 Date: 2/21/92