



NO. N 94-46-2-1

notice of violation

To the following Permittee or Operator:

Name Southern Utah Fuel Company

Mine Convulsion Canyon Surface Underground Other

County Sevier State Utah Telephone (801) 637-4880

Mailing Address P.O. Box P, Salina, Utah 84654

State Permit No. ACT/041/002

Ownership Category State Federal Fee Mixed

Date of inspection 10/31/94, 1994

Time of inspection 8 a.m. p.m. to 4 a.m. p.m.

Operator Name (other than Permittee) NA

Mailing Address NA

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining** is is not expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/ mailing 11/1/94 Time of service/ mailing 12:00 a.m. p.m.

Mike Davis
Permittee/Operator representative
Mailed from Price DOGM Office
Signature

Construction Engineer
Title

Peter Hess
Division of Oil, Gas & Mining representative
Peter Hess
Signature

Engineer II
Title
46
Identification Number

SEE REVERSE SIDE

WHITE-DOGM YELLOW-OPERATOR PINK-OSM GOLDENROD-NOV FILE



NOTICE OF VIOLATION NO. N 94-46-2-1

Violation No. 1 of 1

Nature of violation

- 1) Failure to clearly mark the perimeter of all areas affected by surface facilities before beginning mining activities; (4th East Portals new fan pad installation)
- 2) Failure to maintain perimeter markers as required by R645-301-521.210; (3rd East Portals, Quitchupah Portals, South Portals).

Provisions of act, regulations or permit violated

- 1) R645-301-521.251
 - 2) R645-301-521.210
- (See Continuation Page) →

Portion of operation to which notice applies

- 1) 4th East Portals new fan pad installation area.
- 2) The following portal breakout areas;
 - 1) 3rd East Portals
 - 2) Quitchupah Portals
 - 3) South Portals

Remedial action required (including any interim steps)

- 1) Install perimeter markers as required by R645-301-521.251 in the four areas aforementioned and maintain them according to R645-301-521.210.

Abatement time (including interim steps)

- 1) Perimeter markers should be installed by no later than November 15, 1994 at 5:00 P.M.



NOTICE OF VIOLATION NO. N 94-46-2-1
(Continued)

Violation No. 1 of 1

Nature of violation

3) Failure to provide a certified map of surface facilities (portal breakouts and fan installation).

Provisions of act, regulations or permit violated

- R 645-301-512.120
- R 645-301-521.165
- R 645-301-521.143
- R 645-301-521.180

Portion of operation to which notice applies

- 1) 3rd East Portals (2 breakouts)
- 2) Quitchupah Portals (2 ") and pipeline corridor.
- 3) 4th East Portal & new fan pad installation area
- 4) South Portals (2 breakouts)

Remedial action required (including any interim steps)

2) 1) Submit certified maps of the four aforementioned areas as required to the Division for approval. by

Abatement time (including interim steps)

Submittal date no later than 12/1/94 at 5:00 P.M.