



Canyon Fuel Company, LLC  
SUFCO Mine  
397 South 800 West  
Salina, UT 84654  
(435) 286-4880 Fax: (435) 286-4499

April 4, 2001

Mr. Don Ostler, Director  
Department of Environmental Quality  
Division of Water Quality  
288 North 1460 West  
P.O. Box 144870  
Salt Lake City, Utah 84114-4870

*Copy have Hardy  
FAX AFO  
DMR info*  
~~\_\_\_\_\_~~  
~~\_\_\_\_\_~~

RE: NPDES PERMIT UT-0022918

Dear Mr. Ostler:

According to the conditions of NPDES Discharge Permit UT-0022918, Part II-I-3 and Utah Coal Mining Rules R645-301-731.223, Canyon Fuel Company is providing the written notification of a failure to comply with the daily maximum limitation for Iron at outfall 002. The receiving stream for outfall 002 is East Spring Canyon.

The daily maximum limit for iron of 1.0 mg/l was exceeded because the sample taken on March 21, 2001 had an iron value of 1.17 mg/l. The cause of this high iron is not known. The results of the March 21, 2001 sample were obtained by fax on April 03, 2001 at 3:16 p.m.

Sincerely,  
CANYON FUEL COMPANY, LLC  
SUFCO Mine

Wesley K. Sorensen, P.E.  
Technical Services Manager

cc: Division of Oil, Gas & Mining  
EPA - Water Management Division  
Ken May  
Chris Hansen