



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

PGC
by
OK

Michael O. Leavitt
Governor
Kathleen Clarke
Executive Director
Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

INSPECTION REPORT

Partial _____ Complete XXX Exploration _____
Inspection Date: 04/30/2002 Time: 9:45am-1:30pm
Date of Last Inspection: 03/27/2002

Mine Name: SUFCO Mine County: Sevier Permit Number: C/041/002
Permittee and/or Operator's Name: Canyon Fuel Company
Business Address: 397 South 800 West, Salina, Utah 84564
Company Official(s): Mike Davis
State Official(s): Stephen J. Demczak Federal Official(s): None
Weather Conditions: Warm, 60's
Type of Mining Activity: Underground XXX Surface Prep Plant Other
Existing Acreage: Permitted 24632.95 Disturbed 27.364 Regraded _____ Seeded _____
Status: Active

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b. SEDIMENT PONDS AND IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
c. OTHER SEDIMENT CONTROL MEASURES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
d. WATER MONITORING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
e. EFFLUENT LIMITATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL ISSUES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS CHECK (4 th Quarter- April, May, June)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. AIR QUALITY PERMIT	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. BONDING & INSURANCE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

INSPECTION REPORT
(Continuation Sheet)

PERMIT NUMBER: C/041/002

DATE OF INSPECTION: 04/30/2002

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The Division has received an amendment to open a portal, Link Canyon. This amendment is scheduled to be reviewed by May 20, 2002. This new portal is to be used to reset the sub-station at Link Canyon and to be used as emergency escape-way.

2. SIGNS AND MARKERS

The disturbed area markers were spot-checked and located around the perimeters of the disturbed area.

3. TOPSOIL

The topsoil piles were inspected with no signs of erosion taking place. The topsoil pile at the coal refuse site was well vegetated with grasses.

4A. HYDROLOGIC BALANCE: DIVERSIONS

The diversions were spot inspected with no water flow. The diversions complied with the R645 Coal Rules.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The sediment ponds were inspected with no hazardous conditions noticed. The mine site sediment pond was inspected on March 27, 2002 and the refuse pond inspected on March 25, 2002. The permittee has conducted an annual sediment pond inspection on September 27, 2001. This report was P.E. certified by Wesley K. Sorensen Badge No. 159457. No hazardous conditions were reported.

4D. HYDROLOGIC BALANCE: WATER MONITORING

The permittee has entered the fourth quarter water information into the Electronic Water Data System. There is no water monitoring for the first quarter.

4E. HYDROLOGIC BALANCE: EFFLUENT LIMITATIONS

The UPDES permit UT0022918 expires on April 30, 2006. The point discharge sites 001A and 002A did not discharge in March. The mine site sediment pond 003A did discharge for the month of March and was in compliance with the permit.

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

The refuse pile was inspected by the permittee for the first quarter on March 25, 2002. This report was P.E. certified by Wesley K. Sorensen Badge No. 159457.

8. NONCOAL WASTE

The area was basically clear of non-coal waste material

INSPECTION REPORT
(Continuation Sheet)

PERMIT NUMBER: C/041/002

DATE OF INSPECTION: 04/30/2002

18. SUPPORT FACILITIES/UTILITY INSTALLATIONS


The permittee was in the process of adding two 10,000-gallon culinary water tanks. These tanks are to supply additional water to the bathhouse. The Division approved this project last year.

21. BONDING AND INSURANCE

The inspector reviewed the insurance accord form. The insurance has an expiration date of July 31, 2002.

The Bond is for the amount of \$3,988,000.

Inspector's Signature: _____


Stephen J. Demczak #39

Date: May 1, 2002

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM
Ken May, Canyon Fuel
Price Field office

O:\041002.CON\Compliance\2002\c_0430.doc