



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor
Kathleen Clarke
Executive Director
Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

Handwritten initials/signature

INSPECTION REPORT

Partial XXX Complete ___ Exploration ___
Inspection Date: 06/18/2002 Time: 9:00am-12:00pm
Date of Last Inspection: 05/28/2002

Mine Name: SUFCO Mine County: Sevier Permit Number: C/041/002
Permittee and/or Operator's Name: Canyon Fuel Company, LLC.
Business Address: 397 South 800 West, Salina, Utah 84564
Company Official(s): Mike Davis
State Official(s): Stephen J. Demczak Federal Official(s): None
Weather Conditions: Hot, Sunny, 80's
Type of Mining Activity: Underground XXX Surface ___ Prep Plant ___ Other ___
Existing Acreage: Permitted 24632.95 Disturbed 27.364 Regraded ___ Seeded ___
Status: Active

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: Item, EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include categories like PERMITS, TOPSOIL, HYDROLOGIC BALANCE, EXPLOSIVES, etc.

INSPECTION REPORT
(Continuation Sheet)

PERMIT NUMBER: C/041/002

DATE OF INSPECTION: 06/18/2002

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The permittee has only the Link Canyon Portal amendment at the Division for review.

4A. HYDROLOGIC BALANCE: DIVERSIONS

The diversions were spot inspected and complied with the R645 Coal Rules. The diversions were dry during the inspection. The permittee had recently cleaned out the diversions above the offices along the road to the water tank and sub-station.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The mine site pond was discharging and the refuse sediment ponds were dry. No hazardous conditions were noticed.

4D. HYDROLOGIC BALANCE: WATER MONITORING

The permittee was informed that the Division would not accept "No Access" to a water-monitoring site as a way of complying with the MRP or the R645 Coal Rules.

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

The refuse pile was inspected and no hazardous conditions were noticed.

8. NONCOAL WASTE

The disturbed area was generally clear of non-coal waste material.

18. SUPPORT FACILITIES/UTILITY INSTALLATIONS

No new construction has taken place since the last inspection.

Inspector's Signature: _____

Stephen J. Demczak
Stephen J. Demczak #39

Date: July 5, 2002

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM
Ken May, Canyon Fuel
Price Field office

O:\041002.CON\Compliance\2002p_0618.doc