



GARY R. HERBERT  
Governor

GREGORY S. BELL  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

### Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

September 13, 2013

Ken May, General Manager  
Canyon Fuel Company, LLC  
597 South SR24  
Salina, Utah 84654

Subject: Sediment Overflow Pond As-Built, Canyon Fuel Company, LLC, Sufco Mine, C/041/0002, Task ID #4393

Dear Mr. May:

The Division has reviewed your application for Sediment Overflow Pond As-Built at the Sufco Mine. The Division has identified deficiencies that must be addressed before final approval can be granted. The deficiencies are listed as an attachment to this letter.

The deficiencies authors are identified so that your staff can communicate directly with that individual should questions arise. The plans as submitted are denied. Please resubmit the entire application by no later than November 13, 2013.

If you have any questions, please call me at (801) 538-5350.

Sincerely,

Daron R. Haddock  
Coal Program Manager

DRH/sqs  
O:\041002.SUF\WG4393\Deficiencies.docm



**State of Utah**  
DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
*Executive Director*

**Division of Oil, Gas and Mining**

JOHN R. BAZA  
*Division Director*

## FINDINGS DOCUMENT

### Utah Coal Regulatory Program

**PID:** C0410002  
**TaskID:** 4393  
**Mine Name:** SUFCO MINE  
**Title:** SEDIMENT OVERFLOW POND AS-BUILT

#### Environmental Resource Information

##### Soils

*Deficiencies Details:*

R645-301-222, Prior to disturbance, the Permittee conducted a site specific soil survey of the overflow pond area (Sec. 2.2.2 p. 2-3), which was to be added to Appendix 2-2 (Sec. 2.2.2 p. 2-8). Please provide the Order I soil survey of the overflow pond soils completed in October 2009 by Robert Long and Mt. Nebo Scientific.

pburton

#### Operation Plan

##### Topsoil

*Deficiencies Details:*

R645-301-233.100, Please include the outslope of the overflow pond as in the narrative of Section 2.2.4.

R645-301-231.400 and R645-301-140, An exhibit is presented in App. 2-2 to verify of the topsoil quantity stored at the overflow sediment pond. The exhibit requires labeling and a legend. The exhibit should provide surrounding topography sufficient to illustrate the situation of the pile.

pburton