



OGMCOAL DNR <ogmcoal@utah.gov>

South Fork of Quitchupah Monitoring

Vicky Miller <vmiller@bowieresources.com>

Wed, Dec 31, 2014 at 7:32 AM

To: "Steve Christensen (stevechristensen@utah.gov)" <stevechristensen@utah.gov>, "Amanda Daniels (amandadaniels@utah.gov)" <amandadaniels@utah.gov>, "Hamilton, Rob -FS (rhamilton@fs.fed.us)" <rhamilton@fs.fed.us>, "OGMCOAL OGMCOAL (OGMCOAL@utah.gov)" <OGMCOAL@utah.gov>

Cc: Wyatt Shakespear <WShakespear@bowieresources.com>, John Byars <jbyars@bowieresources.com>, Vicky Miller <vmiller@bowieresources.com>

As is to be expected access has been limited to the South Fork of Quitchupah, we were unable to get to the site on the December 15, 22 and 26. On December 17 flow was difficult to see as the stream channel was drifted over with snow (170015, 28, 32). The spring upstream of the road culvert were flowing at a rate similar to previous observations (170038). There was additional rock fall in the canyon since the monitoring on December 9th. The ponds had some ice and drifted snow in them but water (liquid) was not present (170011, 14).

Snowfall over the two week period at the mine site was 4.25", we estimate at least double that at South Fork. The snow storm on December 22 produced 1.9" of moisture. A map is included to show the location of mining for the two week period.

If you have questions or require additional information, contact me at this e-mail address or at (435) 286-4481. Vicky

7 attachments



PC170011.JPG

3263K



PC170014.JPG

3297K

PC170015.JPG

3139K



PC170028.JPG
3305K



PC170032.JPG
3222K



PC170038.JPG
3202K

 **Mine Map Dec 28 2014.pdf**
108K