



GARY R. HERBERT  
Governor

SPENCER J. COX  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

### Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

July 1, 2014

Ken May, General Manager  
Canyon Fuel Company, LLC  
597 South SR24  
Salina, Utah 84654

Subject: Revise Soil Storage Pile Quantities, Canyon Fuel Company, LLC, Sufco Mine, C/041/0002, Task ID #4635

Dear Mr. May:

The Division has reviewed your application at the Sufco Mine. The Division has identified deficiencies that must be addressed before final approval can be granted. The deficiencies are listed as an attachment to this letter.

The deficiencies authors are identified so that your staff can communicate directly with that individual should questions arise. The plans as submitted are denied. Please resubmit the entire application.

If you have any questions, please call me at (801) 538-5325.

Sincerely,

Daron R. Haddock  
Coal Program Manager

DRH/sqs  
O:\041002.SUF\WG4635\Deficiencies.docm



GARY R. HERBERT  
Governor

GREG BELL  
Lieutenant Governor

# State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

## Technical Analysis and Findings

### Utah Coal Regulatory Program

**PID:** C0410002  
**TaskID:** 4635  
**Mine Name:** SUFCO MINE  
**Title:** REVISE SOIL STORAGE PILE QUANTITIES

#### Operation Plan

#### Topsoil and Subsoil

##### *Deficiencies Details:*

R645-301-121.200, The volume recovered from the project was 487 cu yds according to the Table on WRDS 3-5. However the subsoil volume on WRDS p. 3-4 was increased by only 406 cu yds. Please cross check these figures for accuracy.

R645-301-521.165, The area covered by the two piles was expanded from 0.05 acres to 0.24 acres. The Underground Development Waste Disposal Site Plan, Map 2, should be modified accordingly.

pburton