



GARY R. HERBERT  
Governor

SPENCER J. COX  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

### Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

September 11, 2014

Ken May, General Manager  
Canyon Fuel Company, LLC  
597 South SR24  
Salina, Utah 84654

Subject: Revision Associated with the Shelters in South Fork, Canyon Fuel Company, LLC, Sufco Mine, C/041/0002, Task ID #4647

Dear Mr. May:

The Division has reviewed your application at the Sufco Mine. The Division has identified deficiencies that must be addressed before final approval can be granted. The deficiencies are listed as an attachment to this letter.

The deficiencies authors are identified so that your staff can communicate directly with that individual should questions arise. The plans as submitted are denied. Please resubmit the entire application.

If you have any questions, please call me at (801) 538-5350.

Sincerely,

Steve Christensen  
Permit Supervisor

SKC/sqs  
O:\041002.SUF\WG4647\Deficiencies.docm



GARY R. HERBERT  
Governor

GREG BELL  
Lieutenant Governor

# State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

## Technical Analysis and Findings

### Utah Coal Regulatory Program

**PID:** C0410002  
**TaskID:** 4647  
**Mine Name:** SUFCO MINE  
**Title:** REVISION ASSOCIATED WITH SHELTERS

#### Environmental Resource Information

#### Historic and Archeological Resource Information

##### *Deficiencies Details:*

The information is not adequate to meet the requirements of this section of the regulations. Prior to approval the following information is required in accordance with R645-301-411.140 and 142, 301-130 and 301-512;

The revised Determination of Effect document signed by the Forest Service and SHPO;

A P. E. certified copy of the map that was provided to employees of the Division and Forest Service for the 8/28/2014 site visit to the shelter (42SV3550) and;

The appropriate revisions to the MRP (Engineering, Archaeological, Subsidence in redline/strikeout not take out). Any revisions to the current technical information in the MRP need to include the names of the qualified persons responsible for such changes.

jheltric