



OGMCOAL DNR <ogmcoal@utah.gov>

Fwd: Subsidence crack repair

Karl Houskeeper <karlhouskeeper@utah.gov>

Mon, Oct 5, 2015 at 2:27 PM

To: Daron Haddock <DARONHADDOCK@utah.gov>, Cheryl Parker <cherylparker@utah.gov>, Lisa Reinhart <lreinhart@utah.gov>, Amanda Daniels <amandadaniels@utah.gov>, OGMCOAL DNR <OGMCOAL@utah.gov>

----- Forwarded message -----

From: **Wyatt Shakespear** <WShakespear@bowieresources.onmicrosoft.com>

Date: Mon, Oct 5, 2015 at 2:14 PM

Subject: Subsidence crack repair

To: "priscillaburton@utah.gov" <priscillaburton@utah.gov>

Cc: "karlhouskeeper@utah.gov" <karlhouskeeper@utah.gov>

Priscilla,

We will repair the subsidence cracks as described in our permit, section 5.2.5 and according to the wishes of the surface owner. The subsidence cracks in-question are not associated with surface water flow.

Regards,

Wyatt Shakespear

Environmental Engineer

Canyon Fuel Company- Sufco Mine

(435) 286-4490

wshakespear@bowieresources.com

--

Karl R. Houskeeper

Environmental Scientist III

Division of Oil, Gas and Mining

319 North Carbonville Road, Suite C

Price, Utah 84501

Phone: (435) 613-3730

Fax: (435) 613-3739

Email: karlhouskeeper@utah.gov

