



OGMCOAL DNR &lt;ogmcoal@utah.gov&gt;

---

## South Fork Quitchupah Monitoring

1 message

**Vicky Miller** <vmiller@bowieresources.com>

Wed, Jan 11, 2017 at 11:18 AM

To: Steve Christensen &lt;stevechristensen@utah.gov&gt;, "Hamilton, Rob -FS (rhamilton@fs.fed.us)" &lt;rhamilton@fs.fed.us&gt;, "Ogmcoal@utah.gov" &lt;Ogmcoal@utah.gov&gt;

Cc: Bryant Bunnell &lt;BBunnell@bowieresources.com&gt;, Vicky Miller &lt;vmiller@bowieresources.com&gt;, Jacob Smith &lt;jsmith@bowieresources.com&gt;

The South Fork is still snow covered, with additional storms throughout the two week period, approximately 8 inches of snow fell at mine site. However, as much as 18" fell in other areas adjacent to South Fork, including the accumulation on the access road of up to 2 feet. Access was attempted on the 27, 30 of December and on the 3 and 5 of January. Temperatures were very cold the first week of January, with winds causing large drifts. We were unable to access the South Fork of Quitchupah during this two week period. Please contact us if you need additional information or have questions.

Regards, Vicky



20170109\_115049.jpg  
5907K