



OGMCOAL DNR <ogmcoal@utah.gov>

Monitoring the South Fork of Quitchupah

Vicky Miller <vmiller@bowieresources.com>

Mon, May 15, 2017 at 10:12 AM

To: Steve Christensen <stevechristensen@utah.gov>, Arati Umarvadia <aumarvadia@utah.gov>, "Hamilton, Rob -FS (rhamilton@fs.fed.us)" <rhamilton@fs.fed.us>

Cc: OGMCOAL DNR <ogmcoal@utah.gov>, Vicky Miller <vmiller@bowieresources.com>, Bryant Bunnell <BBunnell@bowieresources.com>, Jacob Smith <jsmith@bowieresources.com>

We were able to access South Fork on May 3, 5, 9, and 11. The North Duncan Flat Pond was 90% full, the Middle Reservoir Pond was 50 - 75% full and the North Duncan Pond remains dry. South Fork is flowing above and below the road between 50 and 70 gpm. Water was flowing above and below the rock fall and at the confluence of the north and south forks of Quitchupah Creek. The stream channel and springs above the road crossing were not checked due to a prescribed burn in the canyon, the burn will continue through May 19. We will resume checking the springs and upstream channel once the burning is completed. If you need more information or clarification, please contact me at this e-mail address or at the office number listed below. Regards,

Vicky Miller

Environmental Engineer

Sufco Mine

Office – 435 286-4481

