



OGMCOAL DNR <ogmcoal@utah.gov>

South Fork Quitcupah Monitoring

1 message

Vicky Miller <vmiller@bowieresources.com>

Mon, Jun 12, 2017 at 2:19 PM

To: Arati Umarvadia <aumarvadia@utah.gov>, Steve Christensen <stevechristensen@utah.gov>, "Hamilton, Rob -FS (rhamilton@fs.fed.us)" <rhamilton@fs.fed.us>, OGMCOAL DNR <ogmcoal@utah.gov>

Cc: Jacob Smith <jsmith@bowieresources.com>, Bryant Bunnell <BBunnell@bowieresources.com>, Vicky Miller <vmiller@bowieresources.com>

We visited the South Fork on May 30 and 31 and on June 6 and 10th. North Duncan Flat pond had water in it , but the other two ponds were dry. No additional subsidence was observed. The Creek was flowing above and below the road crossing, above and below the rock fall and at the confluence during the four visits. The flow in May was approximately 40 gpm and in June it decreased to approximately 30 gpm. Cattle started moving into the area last week, which likely had an effect on the flow. Please contact me at this e-mail address or the number listed below if you have questions. Regards, Vicky

Vicky Miller**Environmental Engineer****Sufco Mine****Office – 435 286-4481**

5 attachments

**Slide4.JPG**
332K**Slide1.JPG**
341K



DSC00006.JPG
7872K



DSC00032.JPG
7993K



DSC00029.JPG
8000K