



OGMCOAL DNR <ogmcoal@utah.gov>

South Fork of Quitcupah Monitoring

1 message

Vicky Miller <vmiller@bowieresources.com>

Tue, Jul 25, 2017 at 12:34 PM

To: Steve Christensen <stevechristensen@utah.gov>, Arati Umarvadia <aumarvadia@utah.gov>, "Hamilton, Rob -FS (rhamilton@fs.fed.us)" <rhamilton@fs.fed.us>, OGMCOAL DNR <ogmcoal@utah.gov>

Cc: Jacob Smith <jsmith@bowieresources.com>, Bryant Bunnell <BBunnell@bowieresources.com>, Vicky Miller <vmiller@bowieresources.com>

South Fork was visited on July 11, 12 and was inaccessible on July 20 and 21 due to heavy rain. Flow was verified on the 11 and 13 to be approximately 40 gpm at the road crossing and appeared to be at a similar flow rate above and below the rockfall. The water continued on to reach the confluence (photo 172). On the 20 and 21, heavy rain caused rockslides and plugged culverts in the area. Roads were blocked until cleanup crews arrived on Thursday evening. Approximately 1 inch of precipitation fell over a 3 day period at the mine site, estimated precip was 2 -3 inches on Thursday pm on the mountain. If you have questions or need additional information please contact me at this e-mail address or the phone number below. Regards, Vicky

*Vicky Miller**Environmental Engineer**Sufco Mine**Office – 435 286-4481*

4 attachments

**DSC00128.JPG**
8092K**DSC00123.JPG**
7997K



DSC00172.JPG
8051K



DSC00155.JPG
7968K