



GARY R. HERBERT  
Governor

SPENCER J. COX  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

### Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

March 28, 2017

John Byars, General Manager  
Canyon Fuel Company, LLC  
597 South SR24  
Salina, Utah 84654

Subject: Update Legal Information, Canyon Fuel Company, LLC, Sufco Mine,  
C/041/0002, Task ID #5372

Dear Mr. Byars:

The Division has reviewed your application. The Division has identified deficiencies that must be addressed before final approval can be granted. The deficiencies are listed as an attachment to this letter.

The deficiencies authors are identified so that your staff can communicate directly with that individual should questions arise. The plans as submitted are denied.

If you have any questions, please call me at (801) 538-5325.

Sincerely,

Daron R. Haddock  
Coal Program Manager

DRH/sqs

O:\041002.SUF\WG5372 LEGAL\Deficiencies.doc





GARY R. HERBERT  
Governor

GREG BELL  
Lieutenant Governor

# State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

## Technical Analysis and Findings Utah Coal Regulatory Program

**PID:** C0410002  
**TaskID:** 5372  
**Mine Name:** SUFCO MINE  
**Title:** UPDATE LEGAL INFORMATION

### General Contents

#### Legal Description

##### Analysis:

The amendment does not meet the State of Utah R645-301-121.120 and/or R645-301-141 requirements for providing a legal description that identifies the land (on a map) subject to coal mining (and reclamation).

Plate 5-6 incorrectly includes T. 20S., R.5E., Section 33: S1/2S1/2 as part of the lease boundary.

The amendment does not update other maps that show the permit boundary.

##### Deficiencies Details:

The amendment does not meet the State of Utah R645-301-121.120 and/or R645-301-141 requirements for providing a legal description that identifies the land (on a map) subject to coal mining (and reclamation).

Plate 5-6 incorrectly includes T. 20S., R.5E., Section 33: S1/2S1/2 as part of the lease boundary. The map must be corrected to remove this parcel from the lease boundary.

The amendment does not update other maps that show the permit boundary. All other maps in the MRP that include a permit boundary must be updated pursuant to this modification of the legal description.

Ireinhart