

0005

WESCAR, INC.

A Subsidiary of Carbon Industries

File in Wescar's Exp. Summit Co. File

File Copy in Ut. Coal & Energy Dept. File

445 UNION BLVD. SUITE 202 ACT/043/01

LAKEWOOD, COLORADO 80228 TELEPHONE 303-988-2435

Route 2818/79

JWS
MAW



February 6, 1979

Mr. Mike Thompson
State of Utah
Department of Natural Resources
Division of Oil, Gas, and Mining
1588 West North Temple
Salt Lake City, Utah 84116

RE: Drilling Near Coalville, Utah

Dear Mike:

I'm sorry to say that I cannot be of any help concerning the groundwater within our project area. This is primarily due to the fact that very heavy drilling mud was used to drill all of the holes (C-1, C-2 and C-3). The drillers were unable to determine how much, if any, water was encountered. In addition, our geophysical log suite included natural gamma, caliper, gamma gamma density and resistivity logs. Without a spontaneous potential curve combined with the resistivity it is impossible to determine the groundwater penetrated in the hole.

If I can be of any assistance, please contact me.

Sincerely,

Jim Hagerty

Jim Hagerty

JH:elt