

0003



United States Department of the Interior
OFFICE OF SURFACE MINING
Reclamation and Enforcement
BROOKS TOWERS
1020 15TH STREET
DENVER, COLORADO 80202

Route & File
ACT/043/001

MAN JWS
R

qk TJS
LCS
8/20
DWH

JMP SP

July 18, 1980

Mr. Ron Daniels
Coordinator of Mined Land Development
Department of Natural Resources
1588 West North Temple
Salt Lake City, Utah 84116

Dear Mr. Daniels:

Enclosed please find a copy(s) of on-site inspection report. The inspection was conducted within Black Hawk Mine during the period of June 23, 1980.

If you have any questions or problems, please contact this office.

Sincerely,

Thomas E. Ehmett
Acting Assistant Regional Director
Division of Inspection & Enforcement

RECEIVED
JUL 21 1980

DIVISION OF
OIL, GAS & MINING

REGION V ON-SITE INSPECTION REPORT

UTAH COAL AND ENERGY
BLACK HAWK MINE
P.O. Box 37
Coalville, Utah 84017
(801) 968-5901

DATE: June 23, 1980
TIME: 8:30 a.m.
WEATHER: Sunny, warm, and clear
COUNTY AND STATE: Summit, Utah
STATE OFFICIAL: Joe Helfrich
OSM OFFICIAL: Eileen Doherty
STATE PERMIT NUMBER: ACT/043/001

GENERAL COMMENTS

A joint State/Federal inspection was made to determine if any activity had taken place at this mine since issuance of a Cessation Order by Utah Mining Division of Oil, Gas, and Mining (DOGM) on December 19, 1979. A catch basin has been excavated below the disturbed area, above the perennial creek. Flow patterns and water in the basin indicated that runoff from a majority of the site was being retained by the basin. No other activity was noted.

Considerable sloughing is occurring from the gravel pit adjacent to the portals. The east portal is partially covered.

It has been several months since the DOGM has been contacted by the operator to discuss future plans.


EILEEN DOHERTY
RECLAMATION SPECIALIST