

0008


March 12, 1981

Inspection Memo  
to Coal File:

RE: Blackhawk Mine  
Utah Coal & Energy Co.  
ACT/043/001  
Summit County, Utah

The above-mentioned mine operation was given an advisory-inspection on March 9, 1981, by Joe Helfrich, Lee Spencer, Wayne Hedberg and Thomas Tetting. Company representative Clem Cafarelli served as an on-site guide.

Permission was requested to address the problem of a gravel slope failure on the northeast side of portals #1 and 2. It was suggested that three separate trench/diversions be cut into the gravel to drain water away from the portals. Two diversions are to be made into the gravel slope terraces draining water over the hill to the north. A third diversion will be cut roughly perpendicular to portal #1 to allow drainage into a small basin to the west on the lower pad. A breach in the old sedimentation pond was indicated in need of closing.

  
THOMAS N. TETTING  
ENGINEERING GEOLOGIST

cc: Tom Ehmett, OSM  
Clem Cafarelli, Utah Coal & Energy

TNT/btm

Statistics:

See Hiawatha memo dated March 10, 1981.