

12-28-87

File SA

0001

INSPECTION REPORT

INSPECTION DATE & TIME: 12/18/87
4:00 pm to 5:00 pm

Permittee and/or Operators Name: Summit Minerals, Inc.
 Business Address: 221 West 2100 South, Salt Lake City, Utah 84115
 Mine Name: Summit Minerals #1 Permit Number: INA/043/001
 Type of Mining Activity: Underground Surface Other
 County: Summit
 Company Official (s): none
 State Official(s): Rick Summers
 Partial: Complete: Date of Last Inspection: 9/18/87
 Weather Conditions: Clear, cold
 Acreage: Permitted 0 Disturbed 16 Regraded Seeded Bonded 16
 Enforcement Action: N87-13-2-1 issued from Division offices by R. Harden

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	()	()	(X)	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	(X)	()
b. DIVERSIONS	(X)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	(X)	()	()	()
f. EFFLUENT LIMITATIONS	(X)	()	()	()
5. EXPLOSIVES	()	()	(X)	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	(X)	()
7. COAL PROCESSING WASTE	()	()	(X)	()
8. NONCOAL WASTE	(X)	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(X)	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	(X)	()
11. CONTEMPORANEOUS RECLAMATION	()	()	(X)	()
12. BACKFILLING AND GRADING	()	()	(X)	()
13. REVEGETATION	()	()	(X)	()
14. SUBSIDENCE CONTROL	()	()	(X)	()
15. CESSATION OF OPERATIONS	()	()	(X)	()
16. ROADS				
a. CONSTRUCTION	()	()	(X)	()
b. DRAINAGE CONTROLS	(X)	()	()	()
c. SURFACING	(X)	()	()	()
d. MAINTENANCE	(X)	()	()	(X)
17. OTHER TRANSPORTATION FACILITIES	()	()	(X)	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	(X)	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: INA/043/001

DATE OF INSPECTION 12/18/87

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMITS

The operator failed to submit the required bond, insurance, and commitments relative to the Division's permit Decision Package dated July 9, 1987. N87-13-2-1 was issued from the Division offices by staff member R. Harden on 11/24/87. The remedial action requires the operator to submit the above referenced items to the Division prior to February 10, 1987. This issue is currently ongoing and the reader is referenced to the Division correspondence files for additional information relative to this matter.

16d. Roads - Maintenance

During the inspection, it was noted that a temporary drainage control (water bar) had been placed 150 ft. south of the access road bridge. This bar was necessary to insure drainage from the site was diverted to the existing sedimentation pond. Drainage entering the pond had infiltrated and there existed no current (nor evidence of past) discharges from the pond.

Copy of this Report:

Mailed to: John Kathman - OSM Jack Higgins - Summit Mineral, Inc.
Given to: Joe Helfrich - DOGM

Inspectors Signature and Number: R. Summers #15 Date: 12/23/87